

The State of Utah

Department of Natural Resources

Division of Oil, Gas & Mining

ROBERT L. MORGAN Executive Director

LOWELL P. BRAXTON Division Director

OLENE S. WALKER Governor

GAYLE F. McKEACHNIE

Lieutenant Governor

Representatives Present During the Inspection: Company Johnny Pappas Sr. Environmental Engineer Joe Helfrich Environmental Scientist III

Inspection Report

Permit Number:	C0070004
Inspection Type:	COMPLETE
Inspection Date:	Thursday, March 11, 2004
Start Date/Time:	03/11/2004 9:00:00 AM
End Date/Time:	03/11/2004 4:00:00 PM
Last Inspection:	Wednesday, February 18, 2004

Inspector: Joe Helfrich, Environmental Scientist III

Weather: sunny 50

InspectionID Report Number: 204

Reprocessing

Accepted by: dhaddock 03/17/2004

Permitee: CASTLE GATE HOLDING CO Operator: CASTLE GATE HOLDING CO

Site: CASTLE GATE MINE

Address: PO BOX 30, HELPER UT 84526-0030

County: CARBON

Phase III

Permit Type: PERMANENT COAL PROGRAM

Permit Status: ACTIVE

Current Acreages		Mineral Ownership	Types of Operations		
7,619.00	Total Permitted	✓ Federal	Underground		
63.00	Total Disturbed	✓ State	Surface		
29.20	Phase I	☐ County	✓ Loadout		
18.20	Phase II	✓ Fee	✓ Processing		

Report summary and status for pending enforcement actions, permit conditions, Divison Orders, and amendments:

Other

The purpose of this inspection report was to conduct a complete inspection of the Castle Gate facilities. The mine is reclaimed. There are no amendments pending, outstanding permit conditions, or compliance issues.

Inspector's Signature:	Dat	ite ^r	Monday, March 15, 2004

Joe Helfrich, Environmental Scientist III

Inspector ID Number: 1

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining



Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Thursday, March 11, 2004

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENT

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 - a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable.
 - b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- 3. Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
- 4. Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

		Evaluated	Not Applicable	Comment	Enforcement
1.	Permits, Change, Transfer, Renewal, Sale	\checkmark		✓	
2.	Signs and Markers	✓		✓	
3.	Topsoil	✓			
4.a	Hydrologic Balance: Diversions	✓			
4.b	Hydrologic Balance: Sediment Ponds and Impoundments		✓		
4.c	Hydrologic Balance: Other Sediment Control Measures	✓		✓	
4.d	Hydrologic Balance: Water Monitoring	✓		✓	
4.e	Hydrologic Balance: Effluent Limitations		✓		
5.	Explosives		✓		
6.	Disposal of Excess Spoil, Fills, Benches		✓		
7.	Coal Mine Waste, Refuse Piles, Impoundments		✓		
8.	Noncoal Waste	✓			
9.	Protection of Fish, Wildlife and Related Environmental Issues	✓			
10.	Slides and Other Damage		✓		
11.	Contemporaneous Reclamation		✓		
12.	Backfilling And Grading	✓			
13.	Revegetation	✓		✓	
14.	Subsidence Control	✓			
15.	Cessation of Operations	✓			
16.	a Roads: Construction, Maintenance, Surfacing		✓		
16.	b Roads: Drainage Controls		✓		
17.	Other Transportation Facilities		✓		
18.	Support Facilities, Utility Installations	✓		✓	
19.	AVS Check		✓		
20.	Air Quality Permit		✓		
21.	Bonding and Insurance	✓		✓	
22.	Other		✓		

Page 2 of 3

Page 3 of 3

Permit Number: C0070004 Inspection Type: COMPLETE

Inspection Date: Thursday, March 11, 2004

1. Permits, Change, Transfer, Renewal, Sale

The permit was renewed December 24, 1999. The 120 day prior submittal date for renewal would be August 26, 2004.

2. Signs and Markers

Signs containing the required information were posted at access points to the reclaimed areas.

4.c Hydrologic Balance: Other Sediment Control Measures

Surface roughening, vegetation, diversions and water bars are the sediment controls for the reclaimed areas. The current snow depth made the site inaccessable.

4.d Hydrologic Balance: Water Monitoring

Water monitoring data was inspected for the fourth quarter. The fourth quarter 2003 monitoring data (entered electronically) was reviewed by the undersigned. Hard copies of the data for the adit pond discharge were reviewed. Sites B11, 12, 28, and 45 were reported as dry. Attempts to monitor the Hardscrabble and Sowbelly sites have not been successful as they have been frozen and snow covered. The undersigned and Mr. Pappas will visit the sights again in April to collect monitoring data. There was some flow from the underground spring at the # 1 Adit.

SITE LOCATION FREQUENCY DATE SAMPLED

- B12 Hardscrabble Upper Quarterly Dry, 9/10/2003, 12/04/2003
- B11 Hardscrabble Lower Quarterly Dry,9/10/2003, 12/04/2003
- B28 Sowbelly Upper Quarterly Dry,9/10/2003, 12/04/2003
- B45 Sowbelly Lower Quarterly Dry,9/10/2003, 12/04/2003

13. Revegetation

The vegetation at Hardscrabble and Sowbelly has been approved for phase II bond release. Pending the vegetation assessment for this year the Sowbelly site should be eligible for phase three bond release. This year's growth at the #1 Adit has not started yet.

18. Support Facilities, Utility Installations

Attempts to access the reclaimed substations were unsuccessful.

21. Bonding and Insurance

The surety bond is currently set at \$601,333.00 and the Certificate of Insurance is current through June 30, 2004.